

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30.07.2021

Division : Chakia

District : Matihari

Name of the Road : Puraing To Banparuaa

Length (km): 3.700

Scheme/Programme: MMGSY (SC)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	-

Observation Remarks:- At ^{some} two stretches BT surface found damaged

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	U
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

RCC culvert (at ch-1700) ^{wash out} fully damage due to flood. Head wall of H.P. Culvert found not-painted.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- km. post, 200m post - not found.

4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory

Name of Officer:-

Ramod Kumar

Designation:-

EE, Reg. Lab. Sasaram

(Signature)

30/07/2021

(Signature)