

LIII

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

TOLA

Name of Scheme: JAMUI KHARAGIPUR ROAD PANRU CHOWK TO RAJPUT		
Hazards	Flood/Rain / 54. Maintenance	
Division: JAMUI	District: JAMUI	Actual Length (in km): 0.70 km
Damage Length (in km):	Damages Location/Chainage:	
Name of Scheme/Programme:	PMGSY	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	YES
Description of observation :		
e)	Compaction of flanks/slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: Maintenance work done satisfactorily,		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

31.07.21