कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरमंगा—2

पत्रांक 1015 नान्।

दिनांक 05'-08-202/

प्रेषक.

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा—2

सेवा में.

नोडल पदाधिकारी, (3054—एम0आर0) विश्वेश्वरैया भवन पटना।

विषय:- शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत निर्माणाधीन पथ के लिये राशि की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक के संबंध में गैर योजना मद शीर्ष—3054 (नई अनुरक्षण नीति—2018) अन्तर्गत निर्माणाधीन पथ के लिये राशि की अधियाचना विहित प्रपन्न में संलगन कर समर्पित की जा रही है।

अतः श्रीमान् से अनुरोध है कि रू० 82.30552 लाख (कुल बेरासी लाख तीस हजार पाँच सौ बावन) मात्र रूपये का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को ससमय भुगतान किया जा सके।

अनु०:- यथोक्त।

विश्वास्रभाजन

कार्यपालक अभियंता,

ग्रामीण कीर्य विभाग, कार्य प्र0, दरभंगा-2

Requisition Fromat for Scheme Head- MR(3054) under Bihar Rural Road Maintenance policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- RWD Works Division Darbhanga-2

	w	2	 	Т.			
1. Sign	-	20/D		+	No S		
ned Hard	-	MR-N/2019- 20/Darbhanga- 2/03	Package No. Name of Road 2 3 L035 Kalwara To Bhapura.				
Copy and So	L035 Bhawanipur 319931034051 To Lorica.	L039 Mankoli Village To Kathalia	L035 Kalwara To Bhapura.	3	Name of Road		
ft Copy (in ex	319931034051	319931036106	319931034052	4	Project ID as per MIS		
1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.	Lt. No-6482 Dt13.12.2019	Lt. No-6482 Dt13.12.2019	Lt. No-6482 Dt13.12.2019	5	Approval (AA) Letter No & Date	Administration	
IRI is er	0.900	1.600	2.550	6	Length (In Km)		
iclosed.	28.81420	47.79710	81.77100	7	Amount of (In Lakh)	Administrative Approval (AA)	
	17.94551	32.65831	51.38035	8	Initial Rectification with Surface Renewal (In Lakh)	Agreeme (In	
	7.46069	13.04929	21.12645	9	5 Years Routine Maintenance (In Lakh)	Agreement Amount (In Lakh)	
		54/MBD20-21 Dt-15.09.2020					
		14.09.2021		11			
		14.09.2021		12	Actual Date of Completion	Actual Date Value of IRI of Completion (in mm/km)	
1	3363	3391	3439	13			
	25mm	25mm	25mm	14	Thickness of Bitumen Layer (In mm)	Thickness of Bitumen Layer (In mm)	
科社	55 5.4		55	15	Value of Bitumen Content in Percentage		
कुल अ	0.0000.0	0.00000	0.0000.0	16	Previous Toatal Alloted Amount (in Lakh)		
कुल अधियाचित राशि=	0.00000	0.00000	0.00000	17	up to date expenditure as per MIS (in Lakh)		
ti= 82.30552	14.50939	27.11432	40.68181	18	Requisition against work done (In Lakh)		
2 लाख।	कार्य पूर्व		कार्य पूर्ण	19	Remarks		

2. Up to date Physical Progress has been uploaded in MIS

Divisional Accounts Officer
R.W.D. Works Division
Darbhanga-2

FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150)
Form of Utilisation Certificate up to the month of Aug-2021
Head 3054 Account for M.R (New Maintenance Policy-2018) Yojna. Year 2020-21

PIU Darbhanga-2

Sl. No	Maintenance Account for Head 3054 Account for MR R (New Maintenance Policy-2018) Yojna	Sanction No. & Date with Amount (in Rs. Lacs) Additional CEO-cum- Secretary Patna. Letter No-32 We Date- 28.05.2021	Amount Received (in Rs. Lacs) Rs. 143.18572	Particulars Certified that out of Rs 143.18572 lacs received during the years 2021-22 in favour of Ex. Engineer RWD work division Darbhanga-2 a sum of Rs 143.18572 lacs has been utilized for the purpose of Maintenance Account for Head 3054 M.R (New Maintenance Policy-2018) Schemes as given in the margin for which it was sanctioned and
			-	that the balance of Rs 0.00 lacs remaining unutilized at the end of the
	Total		143.18572	period under.

2. Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- i. Works haves been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Constructions materials have tested.
- iv. Measurements have been recorded in the MBs and test check conduction by the Assistant Engineer/ Executive Engineer
- v. All other codal formalities have been observed.

D.VA. O.

R.W.D. Works Division

Darbhanga-2

Executive engineer,

R.W.D. Works Division

phanga-2


			3-2	Length-0.9 KM				Name of Road- L035 Bhwa Contractor Name-Md Murshid Alam														
		Event	ongitude	Latitude	TEGORY Latitu	IRI	OR	Speed				Time	Date									
2+1.136 * X +13					ROAD	mm/km	mm/km		in mm	in km	No.	()										
	X = 3200	Normal	85.25741	25.805	G	3086	2600		260	0.1	67	12:46:7	27/6/21									
	Y = 3767	Normal	86.25655	25.80524		3426	2900	-	290	0.1	67	12: 46: 7	27/6/21									
	(R) RURAL ROAD Good Average <4000 4001-5000	Normal	86.25544	25.80543	G	3086	2600		260	0.1	67	12: 46: 7	27/6/21									
		(R) RURAL I	1						1			86.25244	25.80563	G	3654	3100		310	0.1	67	12: 47: 0	27/6/21
			Normal	86.25145	25.8057	G	3199	2700	1 11000	270	0.1	67	12: 47: 0	27/6/21								
		Normal	86.24941	25.80567	G		2500		250	0.1	67	12: 47: 18	27/6/21									
4001-5000 >5001		Normal	86.24815	25.80657	G				310	0.1	67	12: 48: 0	27/6/21									
		Normal	85.24774	25.80735	G		2900	0.0000000000000000000000000000000000000	290	0.1	67	12: 48: 0	27/6/21									
		Normal	86.24502	25.81023	G	3767	3200	-	320	-	67	12:49:4	-									
						3363	ge IRI						., .,									

Executive Engineer

B. W. D. (W) Division

Darbhanga - 2

-



Executive Enginees

R. W. D. (W) Division

Darbhanga - 2