

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 1411 अतु

दलसिंहसराय/दिनांक 13/07/2021

प्रेषक,

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग,

कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी

सचिव-सह-प्राधिकृत पदाधिकारी

ग्रामीण पथ विकास एजेंसी पटना ।

विषय-

New Maintenance Policy 2018(MR New) योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु **Rs.-15.87655 (Fifteen Lakh Eighty Seven Thousand Six Hundred Fifty Five Rupees)** की आवश्यकता है | अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है |

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-15.87655 (Fifteen Lakh Eighty Seven Thousand Six Hundred Fifty Five Rupees)** उपलब्ध कराने की कृपा कि जाये |

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फ़ॉर्म |
3) IRI Report की छायाप्रति सलग्न |

विश्वासभाजन


13.07.21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PIU(Dalsinghsarai)

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
RM/SA/DAL/19/001																		
1		NH 28 Gangapur se Morwa Prakhari Tak	10105081	1855 / 24.06.2019	2.70	60.28000	33.46000	11.37321	MBD 75/2019-20 16.12.2020		-	-	-	-	0.00000	0.00000	0.00000	
2		NH 28 Panahala Se Rupouli Gaw Tak	10105087		1.90	38.08640	33.46000	17.56215			-	3928	25mm	5.10%	26.76800	26.76800	3.04504	
3		Patel Chowk se Chaghan sabni ke ghar banjhi tola hote hue Mahesi karpuri bandh tak pakki road nirman	32010401024		3.50	118.41100	67.17400	34.81884			-	3767	25mm	5.10%	67.17400	66.79885	0.00000	
4		Raipur Bazar se Bhalbhadrapur Meshi Tak	10105082		3.50	111.14000	66.46900	34.29332				3902	25mm	5.10%	53.17520	53.17520	12.83151	
					11.600	327.917	200.563	98.048							147.11720	146.74205	15.87655	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

Sr Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)

Form of Utilisation Certificate upto July 2021

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1273.78458	1273.78458	Certified that out of Rs-1273.78458 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1206.87415 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-21.32864 Lakh remaining unutilized at the end of period under the time of completion
		1273.78458	1273.78458	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-


- Workers have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- Construction materials have been tested
- Measurments have been recorded in the MB's and test check conducted by the
- All other codal formalities have overserved

3. Physical Progress Achieved

- Construction of Road Works
- Construction of CD Works



Sr.DAO

Rural Works Department,
Works Division Dalsinghsarai


13-07-21

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

File : C:\My\master\Bump April-11041141 Xls. Section No. 24. Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$



[Handwritten signature]
11.4.2024

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event	$Y = 0 * X^2 + 1.136 * X + 132.5$
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			Curve	$X = 4300$
11/4/21	9:48:0	24	0.1	420	0	3700	4200	A	25.712712	85.683955	Curve	$Y = 5017$
11/4/21	9:48:0	24	0.1	480	20.2	3600	4100	A	25.711922	85.684175	Speed Breaker	
11/4/21	9:48:25	24	0.1	520	20.2	3600	4100	A	25.711302	85.684493	Normal	
11/4/21	9:48:25	24	0.1	600	20.2	3650	3940	G	25.710412	85.684225	Normal	(R) RURAL ROAD
11/4/21	9:49:0	24	0.1	340	30.3	3400	3994	G	25.70957	85.683838	Curve	Good
11/4/21	9:49:0	24	0.1	330	30.3	3300	3881	G	25.708673	85.68348	Normal	Average
11/4/21	9:49:0	24	0.1	320	30.3	3200	3767	G	25.70786	85.683182	Normal	<4000
11/4/21	9:49:35	24	0.1	250	30.3	2500	2972	G	25.707422	85.68234	Normal	4001-5000
11/4/21	9:49:35	24	0.1	310	30.3	3100	3654	G	25.70692	85.681497	Curve	Poor
11/4/21	9:50:0	24	0.1	470	20.2	3800	4200	A	25.706793	85.680505	Normal	>5001
11/4/21	9:50:10	24	0.1	600	20.2	3400	3800	G	25.706068	85.679982	Normal	
11/4/21	9:50:10	24	0.1	410	20.2	3200	3600	G	25.70557	85.679258	Normal	
11/4/21	9:50:45	24	0.1	330	30.3	3300	3881	G	25.70545	85.678198	Curve	
11/4/21	9:51:0	24	0.1	350	30.3	3500	4108	A	25.705585	85.677222	Normal	
11/4/21	9:51:0	24	0.1	360	30.3	3200	3700	G	25.70506	85.67648	Speed Breaker	
11/4/21	9:51:20	24	0.1	400	30.3	4000	4676	A	25.704892	85.675487	Curve	
11/4/21	9:51:20	24	0.1	420	30.3	4200	4903	A	25.7043	85.674848	Normal	
11/4/21	9:51:20	24	0.1	370	30.3	3100	3500	G	25.703427	85.674747	Curve	
11/4/21	9:52:0	24	0.1	450	20.2	3800	4200	A	25.702715	85.674242	Normal	
11/4/21	9:52:0	24	0.1	420	30.3	3200	3600	G	25.702137	85.67347	Curve	
11/4/21	9:52:0	24	0.1	340	30.3	3400	3994	G	25.701463	85.672777	Normal	
11/4/21	9:52:31	24	0.1	370	30.3	3200	3800	G	25.70086	85.672188	Curve	
11/4/21	9:52:31	24	0.1	320	30.3	3200	3767	G	25.699915	85.671952	Normal	
11/4/21	9:52:31	24	0.1	340	30.3	3400	3994	G	25.699055	85.671902	Curve	
11/4/21	9:53:6	24	0.1	300	30.3	3000	3540	G	25.69819	85.67182	Normal	
11/4/21	9:53:6	24	0.1	330	30.3	3300	3881	G	25.697658	85.67101	Curve	
11/4/21	9:53:6	24	0.1	550	10.1	3600	3900	G	25.6969	85.670572	Normal	
11/4/21	9:53:41	24	0.1	450	30.3	3300	3800	G	25.696065	85.670285	Normal	
11/4/21	9:54:0	24	0.1	480	20.2	3100	3500	G	25.695255	85.669882	Normal	
11/4/21	9:54:17	24	0.1	580	20.2	3200	3600	G	25.694972	85.668872	Normal	
11/4/21	9:54:17	24	0.1	360	30.3	3600	4222	A	25.694828	85.667978	Culvert	
11/4/21	9:54:17	24	0.1	510	10.1	3500	3900	G	25.694958	85.666902	Normal	
11/4/21	9:55:0	24	0.1	490	20.2	3400	3800	G	25.695072	85.665992	Normal	
11/4/21	9:55:0	24	0.1	450	20.2	3700	4200	A	25.694705	85.665318	Culvert	

AP
11/4/2021

~~प्राप्त~~ No 1410/2020-2021

Schedule XLV-Form No. 134

अथवा और if कोई भी नहीं है
570 - 3.500 km

~~यह प्रवेश के लिए~~

DIVISION

~~आपका~~

SUB-DIVISION

MEASUREMENT BOOK

~~प्राप्त~~ No 1410/2020-2021

Recommendation

Darden 5/5/2024

① bricks masonry within
21 cm (1'3) perfor masonry

$$10 \text{ Nos} \times 2 \times 3.00 \times .400 \times .600 = 14.40 \text{ m}^3$$

2. plastering with cm (1'4)

with all corners

$$\text{Surface } 10 \times 4 \times 3.00 \times .600 = 72.00 \text{ m}^2$$

$$\text{Top } 10 \times 2 \times 3.00 \times .400 = 24.00 \text{ m}^2$$

$$10 \times 11 \times .400 \times .600 = 9.60$$

$$105.60 \text{ m}^2$$

3. painting two

coats with all corners

$$10 \times 4 \times 3.00 \times .600 = 72.00 \text{ m}^2$$

Continuation

2/6/2021