

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
<u>2nd on A/C Bell</u>					
N/W - M/R to road from SH to Chornagal.					
Agency - Sri Anjani Kumar					
Apr No. - 4 MBQ/2020-21					
Date of Mts. - 19.1.21					
Details -					
Repair of L.D. 1 No.					
1. Pav. 100 AB/W					
in CM (1:3) m					
parapet -					
<hr/>					
2 x 6.15 x 0.60 x 0.40					= 2.95 m ³
2. 2nd & third Culvert -					
2 Nos -					
{ 2 x 2 x 7.60 x 0.60 x 0.40					= 7.29
2 Nos					<hr/> 10.24 m ³
2. Plastering with CM					
(1:4) on wall -					
1st No.					
Side - (face)					
2 x 2 x 6.15 x 0.60					= 14.76
4 x 6.15 x 0.40					= 9.84
Side - A x 0.60 x 0.40					= 0.96
					<hr/> 25.56 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(iv) 900 mm octagon - 2 Nos - P-13					
					Rs. 7558.90/E - Rs. 15178 = 10
(v) Boundary pillars - 50 Nos - P-13					
					Rs. 483.77/E - Rs. 24189 = 10
					Rs. 3291.713 = 00
Add -					3944711 = 3916592
Cost + L-Cost					418148 =
13% (+)					Rs. 427423 = 10
					Rs. 36,68,136 = 10
					36,34,670 =
Less - 10%					36,34,670 =
					(-) Rs. 3,66,313 = 10
					Rs. 32,96,823 = 10
					32,71,803 =
Less previous					
Bill (-)					Rs. 27,02,855 = 10
					Rs. 5,93,968 = 10
					5,68,348 =
<u>Matr:</u>					
Arides	5720 Nos				Work has been completed as per specification.
Land -	19.18 m ²				
E/W -	957 m ²				
	cap 5.2.21				19.1.21 J.E.
					19.1.21 A.E.