

05555
212-02

Damage?

Phalaris chloris

RFB No - 1457

Name of Agency - D. L. Rol Engineering & Construction

Scanned with CamScanner

1st on A/C. Bill.

10

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Const. & Five					
Years Maintenance of road					
from Badhara Main road					
to Village Nirpura Talu.					
Agency - M.R.L. Infrastructure					
(Rep - Rajnikant Kumar)					
S/o - Nandlal Prasad					
Vill - Bijam, Dist. - Targui,					
Rajauli, Dist. - Nawada,					
Bihar - 805125.					
No. and Date of Agreement -					
05/SBI/2021-2022 (1/07/21)					

Date of measurement - 4/08/21

(1) Providing Const. of Subgrade & earthen shoulders with approved material obtained from borrow pits with all lifts and leads

all complete job.

CH - 00m to CH - 55m
 $1 \times 30.00 \times 7.40 + 4.05 \times 0.30 = 51.525 \text{ m}^3$
 $10 \times 30.00 \times 4.05 \times 0.30 = 364.500 \text{ m}^3$
 $7 \times 30.00 \times 4.05 \times 0.30 = 255.150 \text{ m}^3$
 $1 \times 16.00 \times 4.05 \times 0.30 = 19.440 \text{ m}^3$
 Total Qty - 690.615 m³

Ad 4/8/21
Nigral 04/00/21
J.E.

⑦ Clearing and grubbing of
Road Land. — do — do
— all complete job.
V.T.M.B.P. — ①
Qty. — 0.56 Hec.

@Pg. 53927.68/Hec. — Pg. 30188=00/-

② Providing const. of embankment
with ~~approved~~ ^{real} approved material
Obtained from borrow pits
with a litt up to 1.5m and
lead up to 1000m. ~~done~~
~~up~~ all complete 5th.

V.T.M.B.P. ———— D: Btg-231.06402
1. 100.00 km³ ———— R8. - 44385 = 00/-

Material statement

1) Soil	1687.554 m ³
2) Stone Aggregate	412.527 m ³
3) Local Sand	176.497 m ³
	Normal

3) LOCAL *Handwritten signature*
Handwritten signature 04/08/25
 J. E.

Executive Engineer
Rural Works Department
Works Division, Danapur