

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Inspecting officer <u>Ratnesh Paswan</u>		Designation of Inspecting officer <u>BE</u>
Date of Inspection : <u>13.08.2021</u>		Division: <u>Shershadi</u>
District :- <u>Baigh</u>	Block:- <u>Amas</u>	Length (km): BT: <u>2.125</u> CC: <u>0.073</u>
Name of Road:- <u>L 031-To 1 To Pahnur (VR10)</u>		Actual date of Completion const/Renewal (DD/MM/YY) <u>10.07.2017</u>
Scheme/Programme & Project ID or Package No:		Name of Agency/Contractor: <u>M/S. Maheshwari Construction</u>
Name of E.E	<u>Shri Ranvir Kumar</u>	
Name of A.E	<u>Shri Arunab Kumar Mandal</u>	
Name of J.E	<u>Shri Asarab Ali</u>	
Sl.NO	Name of item/activity to checked	Grading (S/U)
1	Pavement & Shoulders	
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	<u>S</u>
b)	Riding Quality (Pavement condition index (5/4/3/2) as per annexure 14.7 para 14.9 of operation manual.)	<u>S</u>
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	<u>S</u>
d)	Contraction Joints provided or not (CC Pavement)	<u>S</u>
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthen shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications. Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	<u>S</u>
Details of observation & Remarks:		
<u>Road surface is in good condition</u>		
2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)	
a)	Condition of abutment & Return wall/Wing walls. Slab in RCC culverts	<u>N.A</u>
b)	Condition of Slab, railing & approach of Bridges	<u>N.A</u>
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	<u>S</u>
d)	Condition of Vent Clearance	<u>S</u>

Details of observation & Remarks:	
<u>Hd. culvert is in good condition</u>	
3	Road Furniture/ Road Signage
a)	a) Whether sign boards/informatory/cautionary Board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications) b) Maintenance of Km post/ 200m post and guard stones are maintained.(Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.)
Details of observation & Remarks: <u>Road furniture, Informatory board, Maintenance board is fixed in road. All in good condition. K.M. Post &amp; 200 M. Post is found fixed in road.</u>	
4	Compliance History
a)	Status of ATR's & any others
Satisfactory (S)/ Unsatisfactory (U) <u>S</u>	

If Overall grading is unsatisfactory then :  
Action taken against Agency & Subordinates (if any) give details with references:

ABY  
13.08.2021  
BE

22.08.2021  
(Signature) BE