

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Inspecting officer <u>Dinesh Paswan</u>		Designation of Inspecting officer: <u>E.E</u>
Date of Inspection: <u>18.08.2021</u>		Division: <u>Shergarh</u>
District: <u>Catga</u>	Block: <u>Mohanpur</u>	Length (km): BT: <u>1.42</u> CC: <u>0.030</u>
Name of Road: <u>2047 - 2022 To Bhagwanpur (V.D. 26)</u>		Actual date of Completion: <u>04.05.2018</u>
Scheme/Programme & Project ID or Package No: <u>P.M.G.S.Y., 10502302122</u>		Consolidation/Renewal (DD/M/M/Y)
Name of I.I. <u>Ranvir Kumar</u>		Name of Agency/Contractor: <u>Shri Mitunjoya Kumar</u>
Name of A.E. <u>Shri Akhilesh Kumar Maundal</u>		
Name of J.E. <u>Shri Ashraf Ali</u>		
S.NO	Name of item/activity to be checked	Grading (S/U)
1	Pavement & Shoulders	
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	<u>S</u>
b)	Riding Quality (Pavement condition index (5/4/3/2) as per annexure 14.7 para 14.9 of operation manual.)	<u>S</u>
c)	Whether free from defects such as visible cracks, damage of edges & joints, exposed aggregates for CC Pavement.	<u>S</u>
d)	Contraction Joints provided or not (CC Pavement)	<u>S</u>
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthen shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	<u>S</u>
Details of observation & Remarks: <u>Road surface is satisfactory.</u>		
2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)	
a)	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	<u>S</u>
b)	Condition of Slab, railing & approach of Bridges	<u>N/A</u>
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	<u>N/A</u>
d)	Condition of Vent Clearance	<u>S</u>

Details of observation & Remarks:

R.C.C. culvert is in good condition

3 Road Furniture/ Road Signage

- a) Whether sign boards/informative/cautionary Board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications)
b) Maintenance of Km post/ 200m post and guard stones are maintained (Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.)

S

Details of observation & Remarks:

Road furniture, Informative Board & Maintenance Board are drawn in road & found in good condition. K.M. post & 200m post found drawn in road.

4 Compliance History

- a) Status of ATRs & any others

Satisfactory (S)/ Unsatisfactory (U) S

If Overall grading is unsatisfactory then :

Action taken against Agency & Subordinates (if any) give details with references:

AB
18.08.2021
AB

AB
(Signature) 18.08.21
E-E