

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Inspecting officer	Dinesh Paswan	Designation of Inspecting officer	BB
Date of Inspection	17-08-2021	Division	Shurghat
District	Gaya	Block	Amas
Name of Road	2057-T01 Tokhura Khurd (V.P. 39)	Length (km): BT:	1.569 CC: 0.165
Scheme/Programme & Project ID or Package No.	P.M.G.S.Y. 10502302145	Actual date of Completion const./Renewal (DD/MM/YY)	25.07.2017
Name of I.E.	Sri Ranvir Kumar	Name of Agency/Contractor	Tipu Sultan
Name of A.E.	Sri Arunilash Kumar Mandal		
Name of J.E.	Sri Asraf Ali		

Sl.No	Name of item/activity to be checked	Grading (S/U)
1	Pavement & Shoulders	
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	S
b)	Riding Quality (Pavement condition index (5/4/3/2/1) as per annexure 14.7 para.14.9 of operation manual.)	S
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	S
d)	Contraction Joints provided or not (CC Pavement)	S
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthen shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	S

Details of observation & Remarks:

Road surface is satisfactory.

2 Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)

a)	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	
b)	Condition of Slab, railing & approach of Bridges	
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	S
d)	Condition of Vent Clearance	S

Details of observation & Remarks:

H.P. culvert is in good condition

3 Road Furniture/ Road Signage

- a) Whether sign boards-informatory/cautionary board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications)
b) Maintenance of Km post/ 200m post and guard stones are maintained (Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.)

S

Details of observation & Remarks:

Road furniture, Informatory Board Maintenance Board are fixed in road & found in good condition. K.M. Post with box is found fixed in road.

4 Compliance History

- a) Status of ATRs & any others

Satisfactory (S)/ Unsatisfactory (U) S

If Overall grading is unsatisfactory then :

Action taken against Agency & Subordinates (if any) give details with references:

17.08.2021
AB

(Signature) 17-8-21
E-E