

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Inspecting officer	Dinesh Paswan	Designation of Inspecting officer	P.E.
Date of Inspection	17-08-2021	Division	Shurghat
District	Gaya	Length (km): B.T.	0.565 CC:0.435
Name of Road	1060 - To Beldarbiga (VR 42)	Actual date of Completion	25.06.2016
Scheme/Programme & Project ID or Package No.	PMGSY, 1050230214	Consolidation (DD/M/YY)	
Name of I.A.	Roufina Mahant	Name of Agency/Contractor	M/S Rakeshwar Construction
Name of A.E.	Sr. Arvind Kumar		
Name of J.E.	Sr. Arvind Kumar		
Sl. No	Name of item/activity to be checked	Grading (SU)	
1	Pavement & Shoulders		
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc. as per clause 1901 and 1905 of the specifications.)	S	
b)	Bedding Quality (Pavement condition index (3/4/3/2) as per annexure 14.7 para 14.9 of operation manual.)	S	
c)	Whether free from defects such as visible cracks, damage of edges & joints, exposed aggregates for CC Pavement.	S	
d)	Contraction Joints provided or not (CC Pavement)	S	
e)	Condition of Shoulders/slope, rain cuts & Vegetation clearance (Making up of Earthen shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications. Cutting of branches of trees, shrubs and trimming of grass and weeds etc. as per clause 1913 of the specifications.)	S	

Details of observation & Remarks:
 Road surface is satisfactory.
 Routine maintenance work done in length 0.965 K.M.
 Remaining part of road transferred to R.E.D vide B.E. R.W.D. Shurghat letter no 597 dated 26.08.2016

2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)	
a)	Condition of alignment & return wall/filling walls, Slab in R.C.C culverts	N.A
b)	Condition of Slab, railing & approach of Bridges	N.A
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	S
d)	Condition of Vent Clearance	S

Details of observation & Remarks:

H.P. culvert is in good condition

3	Road Furniture/ Road Signage	
a)	Whether sign boards/informative/guidance board, Road Signs & Pavement road marking are provided and maintained (As per clause 1911 of the specifications)	S
b)	Maintenance of Ken post/ 200mm post and guard stones are maintained (Maintenance of 200 m and Ken meter stones as per clause 1913 of the specifications.)	S

Details of observation & Remarks:

Road furniture, Informative board, Main frame board are fixed in road & found in good condition.
 K.M. post & 200 mm post is found fixed in road

4	Compliance History	
a)	Status of ATRs & any others	S

If Overall grading is unsatisfactory then :
 Action taken against Agency & Subordinates (if any) Give details with references:

19.08.2021
 A.R.

25/8/21
 (Signature)
 E.C.