## **INSPECTION REPORT FOR ROUTINE MAINTENANCE**

Name o	finspecting officer Ram Prabeth Saw T.A. Schehmaraja	Obsignation of Inspecting T. A-officer: R.W.D GVC1eS: Wan				
	Inspection: 18/08/21	Division: Begystraj				
District	:- Begysarai Block:- Barayn	Length (km): BT: + CC 2.2 CC: KM,  Actual date of Completion 01.12.18				
		Actual date of Completion 0/.12.18 const/Renewal (DD/MM/YY)				
Scheme	/Programme & Project ID or Package No:	Name of Agency/Contractor:				
Name o	32010502082 - PMGSY BR-04-074 TEE RAM SeWak SEARL	Cri. Sangy Kumay				
Name o	. Krum ZeMak Zangr	Svi Sanjay Kuman				
Name o	- STITINGS NOPT T	, , , , , ,				
Name o	IJ.E Sydhir Kyongr Singl					
SI.NO	Name of item/activity to checked	Grading (S/U)				
l	Pavement & Shoulders					
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	U				
b)	Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)	-				
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	U				
d)	Contraction Joints provided or not (CC Pavement)	S				
c)	Compaction of Shoulders/slope ,raincuts & Vegetation clearance (Making up of Earthern shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	U				
shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications. Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)  Details of observation & Remarks:  The B.T. Portion from chaodiate o to 0.40 km. approx., B.T.  Surface is clausefed about 20% avec. In rest fast it abijusts a compared to the compared to the area is explosed to a green the green repair,  The C.C. Portion from ch. 0.7 to 2.2 km, little area is explosed to a greenate, need repair,						
2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)					
a) C	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	-				
b) C	ondition of Slab, railing & approach of Bridges	-				
c) Co	ondition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per ause 1909 of the specification )					
d) Co	ondition of Vent Clearance	_				

de	M		-15	•
SKY	M	•	~ 13	

Details o	of observation & Remarks;			
r Co	f times for growing for some to	1. 1 wis Analyt med 18/86/31		
1.10	1.77	1.600161	101010719	
3	Road Furniture/ Road Signage	·· Yun ["	. ((N) 101)	
a)	a) Whether sign boards/informatory/cautionary Board/ Road marking are provided and maintained. (As per clause 1911 b) Maintenance of Km post/ 200m post and guard stones are 200 m and kilo meter stones as per clause 1913 of the specific	of the specifications) maintained (Maintenance of	11 to Uniony	
etails o	of observation & Remarks: Not machtaduéd.			
4	Compliance History			
a)	Status of ATR's & any others			
			Satisfactory (S)/ Unsatisfactory (U)	

Action taken against Agency & Subordinates (if any) give details with referees:

Overall Grading - U

(Signature)

18/8/21 NE.

(Flying squa No.2)