INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Insp	ecting officer Ram Prahesh saw (TA)	Designation of Inspecting T. A officer: R.W.D ムヤリヒジロタカ	
)			
District :- (Befusavaj Block:- Barauni	Length (km): BT: CC: 0:950 K	
	1 - 11-0 - 1	Actual date of Completion 05.12.16	
Scheme/Programme & Project ID or Package No: 32010512016 m·m 654 (Gen)		Name of Agency/Contractor:	
Name of E.E.		m/s mantun kumar	
Name of A.E OM Prakash hupta		RWD/2150227	
Name of J.E Sydhar Kumar Sangh		The state of the s	
SI.NO	Name of item/activity to checked	Grading (S/U)	
1	Pavement & Shoulders		
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	U	
b)	Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)	_	
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	U	
d)	Contraction Joints provided or not (CC Pavement)	\$	
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthern shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	U	
Details of observation & Remarks: This goad is c.c. road. The surface is damaged			
Details of observation & Remarks: This road is c.c. road. The surface is clamated This road is c.c. road. The surface is clamated and exhibe apprepais one seems in about 350 M leath in oliffeent stretches. A shouldon plipe also is not maintained.			
2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of	V .	
a)	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts		
b)	Condition of Slab, railing & approach of Bridges	-	
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	-	
d)	Condition of Vent Clearance		

Q.

pe

etails of	observation & Remarks:	
	in some the effect of the first	
		173/12
	To a mark a confidence	in toget
3	Road Furniture/ Road Signage	- Partin
a)	200 m and kilo meter stones as per clause 1913 of the specifications)	property of the state of the st
etails of	observation & Remarks:	
	observation & Remarks: Not maintained	
4	Compliance History	
a)	Status of ATR's & any others	-
		Satisfactory (S)/ Unsatisfactory (U)
lro ₁	erall grading is unsatisfactory then :	1 1000 31.11
tion tak	en against Agency & Subordinates (if any) give details with references:	are full live and
	i falletis of allering folds all	fraillie - to be f
$\sigma \sim$	erall lprolig - U.	
		(Signature)
	A A	
	le PE18	.8.21
	18/8/21 (Flyi	y squed No.2)
	18/0/E	