

Sl no - 7

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Inspecting officer		Ram Prabhesh Singh (T.A.) Sachin Rajan (A.E.)	Designation of Inspecting officer: T.A. R.W.D circle Sikan
Date of Inspection :		18/8/21	Division: Begusarai
District :-		Begusarai	Block:- Barahi
Length (km): BT: -		CC: 0.75 km	
Name of Road:-		PMHSY Road To Simariya Panchayat	Actual date of Completion 29.9.16 Const/Renewal (DD/MM/YY)
Scheme/Programme & Project ID or Package No:		MMHSY (SC) 32010513012	Name of Agency/Contractor:
Name of E.E.		Ram Sewak Singh	Ram Bala K
Name of A.E.		Om Prakash Gupta	Singh
Name of J.E.		Sudhir Kumar Singh.	RWD/2150979

SL.NO	Name of item/activity to checked	Grading (S/U)
1	Pavement & Shoulders	
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	U
b)	Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)	-
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	U
d)	Contraction Joints provided or not (CC Pavement)	S
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthen shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	U
Details of observation & Remarks: This is complete-pec road. From chainage (from end point) 100m to 200m, chainage 650m to 700m, C.C. surface is damaged and it is exposed to aggregate. In length 500m in village portion width is 3.05m that is less width. Although on the road the traffic is very less, yet it has damaged. Quality of work is poor in about 350m length.		
2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)	
a)	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	-
b)	Condition of Slab, railing & approach of Bridges	-
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	-
d)	Condition of Vent Clearance	-

28

S.No. - 7


Details of observation & Remarks:		
3	Road Furniture/ Road Signage	
a)	a) Whether sign boards/informatory/cautionary Board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications) b) Maintenance of Km post/ 200m post and guard stones are maintained.(Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.)	U
Details of observation & Remarks:		
Not maintained		
4	Compliance History	
a)	Status of ATR's & any others	
		Satisfactory (S)/ Unsatisfactory (U)

If Overall grading is unsatisfactory then :

Action taken against Agency & Subordinates (if any) give details with references:

Overall Grading - U

(Signature)


18/8/21
AE.

18.8.21
(Flying squad No - 2)