tails	of observation & Remarks:		
	Painty un dure on Head also un cleaned	ed wall, and vent	
2. 2. 674 92.	also un cleanio		
3	Road Furniture/ Road Signage		
a)	a) Whether sign boards/informatory/cautionary Board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications) b) Maintenance of Km post/ 200m post and guard stones are maintained. (Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.)	S	
Details of observation & Remarks:			
4	Compliance History		
a)	Status of ATR's & any others		
		Satisfactory (S)/ Unsatisfactory (U)	
If Overall grading is unsatisfactory then : tion taken against Agency & Subordinates (if any) give details with references:			
		CHA - 2202	
	19/8/21	Regionallas.	
	A. P.	Regionallas.	
		furnes	

INSPECTION REPORT FOR ROUTINE MAINTENANCE

	and the same the same			
Name of Inspecting officer Makesh Pd Couple	Designation of Inspecting officer: Executive Experien			
Date of Inspection: 19-08-2029	Division: Narkatiagan J			
District: Betia - Block: Braunaha.	Length (km): BT: 1-20 CC: 0.4			
Name of Road: Lo 22 to Khairatiya.	* Actual date of Completion 18-07-26, const/Renewal (DD/MM/YY)			
Scheme/Programme & Project ID or Package No: 3/80890 2234	Name of Agency/Contractor:			
Name of E.E Sni Ram Deo choudhary	Ravi Ranjan Kumur			
Name of A.E on Md shall d Ashraf				
Name of J.E Sn Vijay Poutof Sigh				
SI.NO Name of item/activity to checked	Grading (S/U)			
1 Pavement & Shoulders				
a) Condition of Surfacing (Condition of Pavement including filling pot holes and patch reparete as per clause 1904 and 1905 of the specifications.)	ir U			
b) Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)	U			
Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	U			
d) Contraction Joints provided or not (CC Pavement)	S			
e) Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthern shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)				
Details of observation & Remarks:				
Between ch o to 200 m ch, Some Pig & F	Patch found, Toring			
of grass is required in shulders.	About som legt of			
Ob grass is required in Shoulders. About som teste of. P. Cc., Miner cracks found in upperlayer.				
2 Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910	of the specification)			
a) Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	NA			
b) Condition of Slab, railing & approach of Bridges	NA			
c) Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	U			
d) Condition of Vent Clearance	V			