

Observation & Remarks:

3	Road Furniture/ Road Signage	
a)	a) Whether sign boards/informatory/cautionary Board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications) b) Maintenance of Km post/ 200m post and guard stones are maintained.(Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.)	S

Details of observation & Remarks:

4	Compliance History	
a)	Status of ATR's & any others	
		Satisfactory (S)/ Unsatisfactory (U) U

If Overall grading is unsatisfactory then :

Action taken against Agency & Subordinates (if any) give details with references:

17/08/20
(Signature)
EE, RWD,
Regional Lab
Pune

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Name of Inspecting officer <i>Enr. Mahesh Pd- Gupta</i>		Designation of Inspecting officer: <i>Ex. Engineer</i>
Date of Inspection: <i>17/08/21</i>		Division: <i>Narakatiyaganj</i>
District:- <i>Bettiah</i>	Block:- <i>Narakatiyaganj</i>	Length (km): BT: <i>1.45</i> CC: <i>0.45</i>
Name of Road:- <i>L034 to Imaliya</i>		Actual date of Completion const/Renewal (DD/MM/YY) <i>02/8/18</i>
Scheme/Programme & Project ID or Package No: <i>BR-37R-608</i>		Name of Agency/Contractor:
Name of E.E	<i>Sh. Randeo choudhary</i>	<i>Sabir Hussain</i>
Name of A.E	<i>Shri Ramnarayan Sah</i>	
Name of J.E	<i>Shri Bipin Kumar</i>	

S.NO	Name of item/activity to checked	Grading (S/U)
1	Pavement & Shoulders	
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	U
b)	Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)	U
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	U
d)	Contraction Joints provided or not (CC Pavement)	S
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthen shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	U

Details of observation & Remarks:

Some pot developed between 0 to 500m chainage due to flood water overflow. At 500m chainage About 60m length of Shoulder damaged due to flood water (left side).

2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of the specification)	
a)	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	NA
b)	Condition of Slab, railing & approach of Bridges	NA
c)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	S
d)	Condition of Vent Clearance	S