INSPECTION REPORT FOR ROUTINE MAINTENANCE

		MITENANCE		
	Inspecting officer Manoj Kymen	Designation of Inspecting T. A. officer: RWD Circle Craya		
Date of 1	Inspection: 14-08-201/	Division: Than Thampur		
District :	- Madhubani Block:- Jhan Tharpur	Length (km): BT: 0.00 CC: 0.800		
Name of	Road:- ARARIYA SANGRAMPUR PANCHAYAT NH.57 DADA POKKAR TO TATPUR BARKI POKHAR VIA Programme & Project ID or Package No: MM627 (OLD), 319 09801019	Actual date of Completion 08/07/2017		
Scheme/	Programme & Project ID or Package No: MMGJY (OLD) 31909801019	Name of Agency/Contractor: M/J VAISHNAVI		
Name of	Critakesh Kumar Singh	Construction & CO		
Name of	A.E Er. Prakash Kant Pankas	001)1171241111 2 02		
Name of				
SI.NO	Name of item/activity to checked	Grading (S/U)		
1	Pavement & Shoulders			
a)	Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair etc as per clause 1904 and 1905 of the specifications.)	S		
b)	Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)	S		
c)	Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.	S		
d)	Contraction Joints provided or not (CC Pavement)	ی		
e)	Compaction of Shoulders/slope, raincuts & Vegetation clearance (Making up of Earthern shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1915 of the specifications.)	S		
Details of	of observation & Remarks: Surface of Road on good	condition		
2	Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 1910 of	the specification)		
a)	Condition of abutment & Return wall/Wing walls, Slab in RCC culverts	N· L		
b)	Condition of Slab, railing & approach of Bridges	N.A.		
с)	Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As per clause 1909 of the specification)	N. A.		
d)	Condition of Vent Clearance	N. A		

Details of	observation & Remarks:			1		
				- 4		*//
				4		
	And the second of the second			e	3.0	
					, IVE	
3	Road Furniture/ Road Signage					
а)	a) Whether sign boards/informatory/cautionary Bomarking are provided and maintained. (As per clab) Maintenance of Km post/ 200m post and guard 200 m and kilo meter stones as per clause 1913 of	ause 1911 of the specif stones are maintained.	ications)		* * * * * * * * * * * * * * * * * * * *	2.
Details of	observation & Remarks:		4	. X		;
	e e e e e e e e e e e e e e e e e e e				/#:	
	W.	. *	1	4		
		ia ii		ė. Št		
*5 7.6	The many services and the services are services and the services and the services and the services are services and the services and the services are services and the services and the services are services are services and the services are services are services and the services are services are services are services and the services are servic	AND THE PROPERTY OF THE PROPER		THE PARTY OF THE P		
4	Compliance History	particular and the second				
a)	Status of ATR's & any others					
	1					5-
				Satisfactory (S)/	Insatisfactory (U)	S

If Overall grading is unsatisfactory then :
Action taken against Agency & Subordinates (if any) give details with refernces: