## INSPECTION REPORT FOR ROUTINE MAINTENANCE

| Name of I   | nspecting officer Pramod Kumer  | Designation of Inspecting EE                                   |
|-------------|---|--|
|             | spection: 20.08.2021  | Division: Reg. Lab Sasaram                                     |
| District :- | Ch. Oli C. Lbi  | Length (km): BT: 0.00 CC: 0.100                                |
| Name of l   | Road: Massid To Narha To Majorgant PWW  | Actual date of Completion OS.01: 2019 const/Renewal (DD/MM/YY) |
| Scheme/P    | Programme & Project ID of Package No. 675Ny, 31600010033  | Name of Agency/Contractor: Raman Kumar Singh                   |
| Name of     | e.e yojesh chaulora lolishra  | 9  |
| Name of     | A.E Sudhir Kumar  |  |
| Name of     | J.E Saguib Ahmad  |  |
| si.no       | Name of item/activity to checked  | Grading (S/U)  |
| 1           | Pavement & Shoulders  |  |
| a)          | Condition of Surfacing (Condition of Pavement including filling pot holes and patch repair<br>etc as per clause 1904 and 1905 of the specifications.)   | S  |
| b)          | Riding Quality (Pavement condition index (5/4/3/<3) as per annexure 14.7 para 14.9 of operation manual.)  | S  |
| c)          | Whether free from defects such as visible cracks, damage of edges & Joints, exposed aggregates for CC Pavement.   | S  |
| d)          | Contraction Joints provided or not (CC Pavement)  | S  |
| e)          | Compaction of Shoulders/slope ,raincuts & Vegetation clearance (Making up of Earthern shoulders as per clause 1903 of the specifications & Rain cuts as per clause 1902 of the specifications, Cutting of branches of trees, shrubs and trimming of grass and weeds etc a per clause 1915 of the specifications.) |  |
|             | e of observation & Remarks:  2) no flance is needed due to gali portion   |  |
| 2           | Cross Drainage (Maintenance of culverts and cause ways as per clause 1909 and 191   | 0 of the specification) N.A.                                   |
| a)          | Condition of abutment & Return wall/Wing walls, Slab in RCC culverts  | -  |
| b)          | Condition of Slab, railing & approach of Bridges  |  |
| c)          | Condition of Hume pipe, head walls in Hume Pipe Culverts including its painting (As peclause 1909 of the specification)   | er   |

Condition of Vent Clearance

| -        | COLUMN TAKEN AND A SECOND PROPERTY. | THE RESERVE OF THE PARTY OF THE |
|----------|-------------------------------------|--|
| raile of | observation                         | & Remarks:   |

## No CD Str. IN GTSNY

| 3     | Road Furniture/ Road Signage   | T                    |
|-------|--|----------------------|
| a)    | a) Whether sign boards/informatory/cautionary Board/ Road Signs & Pavement road marking are provided and maintained. (As per clause 1911 of the specifications) b) Maintenance of Km post/ 200m post and guard stones are maintained. (Maintenance of 200 m and kilo meter stones as per clause 1913 of the specifications.) | υ                    |
| tails | of observation & Remarks:  |                      |
|       | 140 MICHARYGOU -DOCCO  |                      |
|       | No maintenance board<br>Main board in formit but not broken  | rly painted.         |
|       | Main board is found but inch proper  | rly painted.         |
|       | Main board is formit but int broken  | rly painted.         |
|       |  | rly painted.         |
| 4     | Main board is form but int !pmfer  Compliance History  | rly painted.  No ATR |

If Overall grading is unsatisfactory then :
Action taken against Agency & Subordinates (if any) give details with refernces:

(Signature)

EE RWD Reg. lab Savara