

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

|                                            |  |                       |
|--------------------------------------------|--|-----------------------|
| Date of Inspection : 28.11.2021            |  | District: Muzaffarpur |
| Division : Muzaffarpur East-1              |  | Length (km): 2.500    |
| Name of the Road: BMP6 to Kalkatia Banchhi |  |                       |
| Scheme/Programme: New MK                   |  |                       |

| Sl. No.                                                        | Parameters to be checked                                                                                              | Remarks (S/U) |
|----------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|---------------|
| 1.                                                             | Pavement                                                                                                              |               |
| a)                                                             | Condition of Surfacing                                                                                                | S             |
| b)                                                             | Riding Quality                                                                                                        | S             |
| c)                                                             | Road Camber                                                                                                           | S             |
| d)                                                             | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                          | S             |
| e)                                                             | Contraction Joints provided or not (CC Pavement)                                                                      | S             |
| f)                                                             | Compaction of flank/slope & raincuts if any No raincuts.                                                              | S             |
| <b>Observation Remarks:-</b> Surface Condition is Satisfactory |                                                                                                                       |               |
| 2.                                                             | Cross Drainage                                                                                                        |               |
| a)                                                             | Condition of head walls in Hume pipe culverts including its painting                                                  | —             |
| b)                                                             | Condition of Abutment & Wing walls, Slab in RCC culverts                                                              | —             |
| c)                                                             | Condition of railings/slab/approach for Bridges                                                                       | —             |
| d)                                                             | Condition of Vent Clearance                                                                                           | —             |
| <b>Observation Remarks:-</b>                                   |                                                                                                                       |               |
| 3.                                                             | Road Furniture                                                                                                        |               |
| a)                                                             | Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained | S             |
| <b>Observation Remarks:-</b>                                   |                                                                                                                       |               |
| 4.                                                             | Compliance History                                                                                                    |               |
| a)                                                             | Status of ATR's & any others                                                                                          | NO ATR        |

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Basim Kumar Singh

Designature:- Executive Engineer  
RWD, Regional Lab. Bhagalpur.

E.E. Muzaffarpur East 1 - Sri Gyan B. Bhakar

28.11.2021  
(Signature)