INSPECTION REPORT FOR ROUTINE MAINTENANCE

Division: Magaffarpus Fast-1 Length (km): 1.000 Name of the Road: Kudhmi Ponkhami Ke Gova in funda Vishurpus (Ruvi-tala) tak		
St. No.	Programme: MNP- 4515 Parameters to be checked	Remarks (S/U
1.	Pavement	Remarks (5/C
a)	Condition of Surfacing	S
b)	Riding Quality	3
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	5
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any No vain List.	S
a)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting	5
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	, —
c)	Condition of railings/slab/approach for Bridges	_
d)	Condition of Vent Clearance	S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
bserva	ion Remarks:-	e se
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR
verall l	Rating : Satisfactory (S)/ Unsatisfactory (U)	Colifornia C
	Officer. Rana Brown Kleman Singh wre:- Encentive Expinely wre:- Encentive Expinely wrong Lab. Bhofalpu. (Signal Jaspu East 1, Shi byon Bildakor.	Sobifactor S