

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30/11/21 District: East Champaran
 Division : Chakia Length (km): 3.00
 Name of the Road: Shitakhia Kasi Pakri - Theluwaha Path
 Scheme/Programme: New M/R

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating Satisfactory

30/11/21
A.E.
(Ramesh Kumar)

30/11/21
Bindu Rajak
Executive Engineer
Rw. D
Reg. Lab. Darbhanga