

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30/11/2021 District: East Champaran
 Division : Chokia Length (km): 2.02
 Name of the Road: Beethna NH-28 Chakmadori 149
 Scheme/Programme: New M/R

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S


Observation Remarks:-


3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating Satisfactory


 30/11/21
 A.E.
 (Ramesh Kumar)


 30/11/21
 Bindu Rajak
 Executive Engineer
 R.W.D.
 Reg. Lab. Darbhanga