

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30/11/21 District: East Champaran
 Division : Chakia Length (km): 1.90
 Name of the Road: Mirapur PWD Path to Koiragawa Tak
 Scheme/Programme: M.M.C.Sy (Gen.)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	U
a)	Condition of Surfacing	U
b)	Riding Quality	✓
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:- B.T. Portion almost damage due to flood. Temporary restoration work done with bricks bats in different stretches.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating Unsatisfactory

(Signature)
 30/11/21
 A.E.
 (Ramkishan Das)

(Signature)
 30/11/21
 Bmdn Rajak
 Executive Engineer
 P.W.D.
 Reg. Leno Donsbhang