

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30.11.2021		District: Muzaffarpur
Division : Muzaffarpur East-1		Length (km): 2.350
Name of the Road: Mohammad Damodar Dandua Singh ke bazar to Mohammadpur tal se Sindhakar Thakur ke Ghar Tak		
Scheme/Programme: MMSYL NDB-RRICG-I		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any No rain cuts.	S
Observation Remarks:- Surface condition is satisfactory.		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Ram Basu Kumar Singh  
Designation:- Executive Engineer  
RWD, Regional Lake Bhagalpur.

(Signature) 30.11.2021

EE, Muzaffarpur East-1, Sd/- Bygon Bibhakar.