

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.2021
 Division : Muzaffarpur East - I
 District : Muzaffarpur
 Length (km): 6.530
 Name of the Road: TOL - Rohua Pura Road to Rajwar Bhagwan
 Scheme/Programme: PMHSY-II

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	No rain cut S

Observation Remarks:- Surface Condition is Satisfactory.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) Satisfactory (S)

Name of Officer:- Rama Barun Kumar Singh
 Designation:- Executive Engineer
 RWD, Regional Laboratory Bhagalpur.

28.11.2021
 (Signature)

EE, Muzaffarpur East I - Sri Gyan Bibhakar.