

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29/11/2021 District: East Champaran
 Division : Chakia Length (km): 2.00
 Name of the Road: NH 28 Nag Rly. Gumat to Taramiya
 Scheme/Programme: MMASy (Gen)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:- P.C.C. pavement from Km 0 to 1 surface exposed and vegetation found both side

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	U
c)	Condition of railings/slab/approach for Bridges	N.A.
d)	Condition of Vent Clearance	S

Observation Remarks:- parapet not maintained and not painted.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- Road furniture not found

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

unsatisfactory

29/11/21
 (Ramesh Chandra Patra)

29/11/21
 Binod Rajak
 Exe. Eng.
 Regional Lab Berhampur