INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 2611112021 District	: Madhubani
Division: Than That per Length (km): 0.974 km		
Name o	fthe Road: Vaswa to Phylwarto	
Scheme/Programme: MMCSY (Gen)		
Sl. No.	Parameters to be checked	ed Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing U	
b)	Riding Quality	- U -
c)	Road Camber	U _{n se}
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Paven	nent)
f)	Compaction of flank/slope & raincuts if any	-\$-
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	
Observ	ration Remarks:-	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	
Observ	vation Remarks:- el was not maintained Stash der FDR	beforely. Partly motorable
4.	Compliance History	
a)	Status of ATR's & any others	
Over	all Rating	rei K

V.

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:- KUMAR RAKESH तकनोको सलाहकार ग्रामीण कार्य विभाग कार्य अंचल, पटना