

E.E. :- Mukesh Kumar Singh

**INSPECTION REPORT FOR ROUTINE MAINTENANCE**

Date of Inspection : 25/11/2021		District: Madhubani
Division : Jharkhand		Length (km): 0.800 km
Name of the Road: Pakachhubi Rajhat Pul to Mallah tal		
Scheme/Programme: MMGSY- NDBCBRIS-1		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	S
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S/A
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road was found maintained satisfactorily.		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- KUMAR RAKESH

Designation:- तकनीकी सलाहकार  
ग्रामीण कार्य विभाग  
कार्य अंचल, पटना

25/11/21  
ME

(Signature)

25.11.2021