INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 26 11 2021		District: Madherbani	
Division: Than Tharpur Length (km):		ength (km): 0.80 km	
Name of the Road: Moarya Sangrameur Panchayat NH-57 Dada Pokhar to			
Scheme/Programme: MMGSY(old)			
Sl. No.	Parameters to be cl	necked	Remarice (S/U)
1.	Pavement		
a)	Condition of Surfacing		S
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S **
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		S
Observation Remarks:-			30
		3	2
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		2
c)	Condition of railings/slab/approach for Bridges		
d)	*Condition of Vent Clearance		S
Observation Remarks:-			
			-
			and the
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionstones/Pavement road markings are provided		Š.
	tion Remarks:- was maintained Salustaed	toruly	
4.	Compliance History		a de la companya de l
a)	Status of ATR's & any others		- AS
Overall	Rating	2	
Orolan	Satisfactory (S)/ I	Insatisfactory (U)	7

Name of Officer:- KUMAR RAKESH तिकनीको सलाहकार ग्रामीण कार्य विभाग कार्य अंचल, पटना

Luman draft (Signature)