INSPECTION REPORT FOR ROUTINE MAINTENANCE

7.

Date of Inspection: 26/11/2021		District: Machy bani	
Division: Than Tharpur Length (km): 2.38 km			
Name of the Road: Lo23-Lo24 to Malicham			
Scheme/Programme: PM 0.34			
Sl. No.	Parameters to be	checked	Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		V
b)	Riding Quality		Sing
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		Sim
Observation Remarks:-			
Pot paches seen in BT portion at start point of Road			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		3.
c)	Condition of railings/slab/approach for Bridges		
d)	Condition of Vent Clearance		S
Observation Remarks:-			
3.	Road Furniture		
a)	Whether sign boards/informatory/caut stones/Pavement road markings are pro		U.F
Observation Remarks:- Road was not mantamed satisfactoruly			
4.	Compliance History		
(a)	Status of ATR's & any others		Petage .
Overall Rating : Satisfactory (S)/ Unsatisfactory (U)			

Name of Officer:- Kunda RAKES Designature:- ग्रामीण कार्य विभाग

कार्य अंचल, पटना

26/11/21 dry 6.1. (Signature)