## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 76 1112021 District: Madhuban				A
Division: Than that put Length (km): 1.20 km				
Name (	of the Road: PWD H	igh School Nanaus		
	e/Programme:	VABARD	or was a substitution of the substitution of t	
Sl. No.		Parameters to be checked		Remarka (S/U)
1.	Pavement			
a)	Condition of Surfacing		S	
b)	Riding Quality		2	
c)	Road Camber		S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			S
e)	Contraction Joints provided or not (CC Pavement)			S
f)	Compaction of flank/slope & raincuts if any			8.8
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			<u> </u>
d)	. Condition of Vent Clearance			S
Observa	tion Remarks:-			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained			S
Observa Roae	tion Remarks:- was found or	nountained Seulis	factorely.	
4.	Compliance History			
a)	Status of ATR's & any others			
Overall	Rating :	Satisfactory (S)/ Unsatisfa	actory (U)	100°S

Name of Officer:- KUMAR RAKES H Designature:- तकनीकी सलाहकार

ग्रामीण कार्य विधान कार्य डॉक्ल, भटा। 26/11/21 (Signature)