

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 11/12/21		District: Arany
Division : R.W.D Arany		Length (km): 3.718 km
Name of the Road: PMGSY Mukhiya tal to Galua tal		
Scheme/Programme: MMGSY (WB)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT 4 CC	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
Observation Remarks:- R.E.C. culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, km. post and 200m post is fixed in road		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ratnesh Paswan
 Designature:- E-E

20/11/21
 11-12-2021
 (Signature)

ARBY
 11/12/21
 AR