

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 09/12/2021	District: Madhubani
Division : Jhanjharpur	Length (km): 1.654 km
Name of the Road: Lila-Bharna via Tengoh	
Scheme/Programme: PMGSY	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

Road was not maintained. Pot holes seen at different channage.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- Road was not found maintained
Potholes seen at different channages.

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- KUMAR RAKESH

Designature:-

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

09/12/21
A.B.

(Signature)

09.12.21