

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 10/12/2021		District: Madhubani
Division : Jhargharpur		Length (km): 0.937 km
Name of the Road: Passa Main Road to Dhanuik tola		
Scheme/Programme: MMGSy (SC)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- <p style="text-align: center; font-size: 1.2em;">Road condition was not satisfactory</p>		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Neither the road condition was satisfactory nor the maintenance work was going on.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- KUMAR RAKESH

Designature:-

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

10/12/21
R.E.

(Signature)

10-12-21