

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 10/12/2021		District: Madhubani
Division : Jhangharpur		Length (km): 9.80 km
Name of the Road: Repair of road from Pipraghat to Fulparas		
Scheme/Programme: MR		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> <p style="text-align: center; font-size: 1.2em;">Road condition was not satisfactory</p>		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b>		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b> Neither the road was maintained nor the maintenance work was going on.		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- KUMAR RAKESH

Signature:-

तकनीकी सलाहकार  
ग्रामीण कार्य विभाग  
कार्य अंचल, पटना

10/12/21  
A.E.

(Signature)

10.12.21