

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 10/12/2021		District: Madhubani
Division : Jhangharpur		Length (km): 0.610 km
Name of the Road: REO Khadawa Road se chaupal tal Radhenandanpur		
Scheme/Programme: MMGSY		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- <p style="text-align: center; font-size: 1.2em;">Road condition was satisfactory</p>		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Over all road condition was satisfactory. Length of road only 0.610 km.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- KUMAR RAKESH

Designature:-

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य संचालन

10/12/21
A.E.

(Signature)

10.12.21