

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 10/12/2021		District: Madhebari
Division : Jhanjharpur		Length (km): 1.0 km (0.600km)
Name of the Road: Koryahi tola Mukhya Sadak to Durga Asthan tak path		
Scheme/Programme: NABARD		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road was found satisfactory		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- 600m PCC road condition was found satisfactory. Only this much length was constructed under NABARD.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- KUMAR RAKESH

Designature:- तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

10/12/21
 K.R.

(Signature)