

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 09/12/2021		District: Madhubani	
Division : Jhangharpur		Length (km): 1.125 km	
Name of the Road: Madhepur Triveni chaur to Yadav tal			
Scheme/Programme:		MMGSY- NDB (BRICS)-1	
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement		
a)	Condition of Surfacing	S	
b)	Riding Quality	S	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—	
e)	Contraction Joints provided or not (CC Pavement)	—	
f)	Compaction of flank/slope & raincuts if any	S	
Observation Remarks:- Road was found maintained and satisfactorily.			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	
c)	Condition of railings/slab/approach for Bridges	—	
d)	Condition of Vent Clearance	S	
Observation Remarks:- 			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S	
Observation Remarks:- Maintenance of road done satisfactorily.			
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- KUMAR RAKESH

Designation:-

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य विभाग

Signature
09/12/21
RE

(Signature)

Signature
09.12.21