

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 09/12/2021		District: Madhubani
Division : Jhargharpur		Length (km): 0.683 km
Name of the Road: Matous more to Matous Punagwas		
Scheme/Programme:		


Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> Road was found maintained and satisfactory		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b>		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b> Road condition was found satisfactory.		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- KUMAR RAKESH  
 Designation:- ग्रामीण कार्य विभाग  
 कार्य अंचल, पटना

  
 09/12/21  
 A.E.

(Signature)