

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 11-12-21		District: Aranyas
Division : F.W.D. Aranyas		Length (km): 2.60 km
Name of the Road: Giryamad Munda to Gaiyari Tola		
Scheme/Programme:		MMGSY (GEN)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
e)	Contraction Joints provided or not (CC Pavement)	N/A
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Road surface (B.T) side edge damaged due to over top of flood water & wash out at ch. 750 to 820 M and ch - 1320 to 1370 and 240 to 2430 M.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
Observation Remarks:- R.C.C culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, K.M. Post and 200 M Post is fixed in road		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Ratnesh Paswan
 Designature:- E. E.

11/12/2021
 (Signature)

11/12/2021
 AB