

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 11/12/2021 District: Vaishali
 Division : Hajipur Length (km): 1.34
 Name of the Road: Mathurapur Kusadae gram to avadh bihari singh college tak.
 Scheme/Programme: MMBSY (SC)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:-

BT portion damaged due to flood
 Flank not done in PCC portion.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

3/3
 11/12/2021

Designation:-

E.E.

SIA
 11/12/21
 A.E.