

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 11/12/2021 District: Vaishali
 Division : Hagi pur Length (km): 1.41
 Name of the Road: Lalgang hagi pur Road ke nemiditi pipal tree to
 Scheme/Programme: NABARD Kothaha gram sima tak.

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U S

Observation Remarks:-

flank not done due to
private land

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—

Observation Remarks:-

N.A.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ ker & John stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

[Signature]
11/12/2021

Designation:-

E-E

[Signature]
11/12/21
A-E