

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 13-12-2021	District: Aranyga
Division : R.W.D. Aranyga	Length (km): 5.334 km
Name of the Road: LOR - TOI TO KURHAILLI (VR 26)	
Scheme/Programme: P.M.G.SY.	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:- BT surface Damaged & Pot developed at ch - 1000 to 1100 & 1500 to 1530 and road wash out at ch 1700 to 1720, 2200 to 2230 & 3400 to 3600 m due to over top of flood water. C.C. surface is satisfactory.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A

Observation Remarks:-

N.A

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:- Road furniture ; Informatory & Maintenance board, km post and 200m post is provided in road

4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designature:-

AKB
13-12-21
AR

[Signature]
13-12-2024
(Signature)
E-E