

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 9/12/21	District: Vashi
Division : Hugi per	Length (km): 1.50
Name of the Road: Construction of road from Panthayat Main Bairo in Gram Muzaffarpur Malahi (Paschim) Mahadeli & other Backward Cast.	
Scheme/Programme: SCP (MMWS) New Maintenance	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

CCP. NA.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

9/12/21
A.E.

Designation:-

9/12/21
A.E.