

INSPECTION REPORT FOR ROUTINE MAINTENANCE

3

Date of Inspection : 09/12/2021

District: Vaishali

Division : Hagi pur

Length (km): 0.155

Name of the Road: House of Nandkishor Sah To House of Rag'dev Sah

Scheme/Programme: GTSNY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

CCP damaged.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-

Observation Remarks:-

N.A.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating : Work resinded.

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

3/3
9/12/2021

Designation:-

E.E.

San
09/12/21
A.G