

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 13-12-2021		District: Arany
Division : R.W.D. Arany		Length (km): 1.10 km
Name of the Road: P.M.G.S.Y. To Mandal Tola Tak		
Scheme/Programme: M.M.G.S.Y (Gen)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T & C.C.	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
Observation Remarks:- R.C.C culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained.	S
Observation Remarks:- Road furniture; Informatory & Maintenance Board, km & 200m post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Designature:-

AB
13-12-2021
AB

2-2/11
13-12-2021
(Signature)
E-E