

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 09/12/2021		District: Vaishali
Division : Hajipur		Length (km): 2.02
Name of the Road: Ratanpur Math NH-77-Asoi Market.		
Scheme/Programme: PMWY/NEA (New Maintenance 2018)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- CCP N.A.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No
Overall Rating :		Satisfactory (S)/ Unsatisfactory (U) S
Name of Officer:-		9/12/21
Designation:-		E.E.