

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14/12/2021 District: Supaul
 Division : VITPUR Length (km): 6.63
 Name of the Road: Repair of Road from Gormd pur to Araraha
 Scheme/Programme:

Sl. No.	Parameters to be checked	Remarks (S/I)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:- B.T. Surface Damage at two points in length 5m ~~to~~ 10m due to water logging and

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 100m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory

14/12/21
 (Ramkishan Kumar)

14/12/21
 Bindu Rajak
 Executive Engineer
 RWD Regional Laboratory
 Darbhanga