

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15.12.2023

District: Kailash

Division: Barahat

Length (km): 3.75

Name of the Road: Repair of road from Patol to Maloo

Scheme/Programme: MP-3054

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any, NO rain cuts.	S

Observation Remarks:- Surface condition is satisfactory. In flank there is no rain cuts.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Basu Kumar Singh
 Designation:- Executive Engineer, Road & Ld. Bhagalpur.

15.12.2023
 (Signature)