

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15.12.2021 District : ~~BB~~ Kothikeri
 Division : B&R02 Length (km): 14.45
 Name of the Road: MRIOL - Agkunathpur to Adampur
 Scheme/Programme: PMBSV II

Sl. No.	Parameters to be checked	Remarks (S/U)
1. Pavement		
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any <u>No rain cut</u>	S

Observation Remarks:- Surface condition and riding quality is satisfactory. In flank there is no rain cut.

2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4. Compliance History		
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Arav Bhaun Kumar Singh
 Designature:- Executive Engineer, B&R Div. B&R02

15.12.2021
 (Signature)