

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 16.12.2021

District: Katihar

Division : Bara

Length (km): 0.480

Name of the Road: Khir Khurya Chowk to Durgapur

Scheme/Programme: MMHSY(ST)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any no rain cuts	S

Observation Remarks:- Surface condition is Satisfactory and there is no rain cuts in flank.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Bouson Kumar Singh
Designature:- Executive Engineer, Regional Lab. Bhagalpur

16.12.2021
(Signature)